

# **Advantech Corporation**

## **EKI-7700/EKI-7400 Series**

### **Release Note**

- **Firmware version: v1.00.97**

<b>Release Date</b>	2017/07/03
<b>Engineer</b>	Robert.Chung
<b>Final Approval</b>	JasonC.Chiou

## **I. Release Brief**

Firmware Version: v1.00.97

Purpose of Release: Bug fixed.

Customer: Advantech

## **II. Changes**

### **i. New Feature Release**

- a. Add IXM support group setting
- b. Change image name to "Synchronized via IXM" while upgrade firmware via firmware sync of IXM.
- c. Prompt support sysname, syscontact, syslocation
- d. LED Indication add Port Link-down mode.
- e. QinQ behavior change. add new command "[no] vlan qinq"
- f. Add X-RING Chain, X-RING Pair, function

### **ii. Bugs Fix**

- a. Fix Loop detection function bug
- b. Fix DDM web gui or refresh the vendor info will occurs operation system crash.
- c. Fix X-Ring link partner's link down message cause ring port short time loop bug.
- d. Fix utility always getting first partition image via IXM.
- e. Fix click DDM web page that will make system crash, when the CPU on busy.
- f. Fix DDM alarm is unavailable bug.
- g. Fix user unable to configure LED Indication settings by WEB GUI bug.
- h. Fix If one of the image partition wrote failed, to click dual image web page unable to display bug.
- i. Fix after IXM config synchronization retry succeed, it always direct wrote synchronization config into target device running config.
- j. Fix IXM firmware synchronization always use partition 0 on source device
- k. Fix the Fiber auto sensing speed detection is unstable on 100Mbps SFP module bug.
- l. Fix IXM image file unable to backup from device via HTTP by WEB bug.
- m. Fix port mirror status information table displays incorrect on WEB bug.

- n. Fix user can not configure the the coupling ring parameter via web gui bug.
- o. Fix retry Config Synchronization does not works, if user select Xring-Pro feature for synchronization bug.
- p. Fix when the MSTI ID is removed the BPDU packet still with the MSTI ID and different MST interface send out the BPDU packet with common MSTI ID bug.
- q. Fix compatible issue between IE11 and IXM.
- r. Fix Network Time Protocol (NTP) polling period is 30 seconds may cause NTP server crash bug.
- s. Fix X-Ring Pro Groups Settings or Couple Setting successful but is getting a 502 Bad Gateway error bug.
- t. Fix SNMP query the private MIBs (systemTime and sfp) will make the SNMP agent timeout and the device CPU utilization rate arrive 80% ~ 9X% at period of time bug.
- u. Fix STP is enabled in startup config will cause NTP can't get time from server at device boot up bug.
- v. Fix telnet session still exist in switch after changing IP address.
- w. Fix once user executes save configuration then reboot system, the parameter of LLDP TX-Delay will not been saving.
- x. Fix X-Ring topology receives LLDP packets that will circulate endlessly around the loop bug.

### iii. The known unfixed issues

N/A

### iv. MD5 checksum

MD5 EKI-7700\_v1.00.97.hex = 6c7a1f32ba6ff453b94b33f30f95846e