

MIO-5290 Errata

MIO1: HDMI/DP hot plug function doesn't work.

Problem:

When plug in HDMI/DP monitor, the monitor cannot be detected.

Implication:

Due to hardware design, hotplug function is not supported. User has to plug the cable to the system before booting up the system.

Workaround:

Modify circuit to support hotplug function. Please contact your local FAE for detail information.

ESBC support team 2015.08.11