

# Advantech AE Technical Sharing Documentation

Date	2018 / 10 / 19	SR#	1-3584329961
Category	■ FAQ □ SOP	Related OS	N/A
Abstract	Notification: The new version mainboard of UNO-1372G-J		
Keyword	SIM card slot position changed		
Related Product	UNO-1372G-J		


## ■ Problem Description:

We are about to release an ECOM for changing motherboard to a new version.  
The SIM card slot position has been changed in the new version of motherboard.

**ECOM-146522**



## ■ Brief Introduction

1. The original mainboard position of the SIM slot.



**Figure A.1 Connector & Switch Locations on MB(Top)**

2. The new version mainboard position of the SIM card slot.



■ **Contact Window and File Link:**

If you have any questions, please contact [Jerry.Cheng@advantech.com.tw](mailto:Jerry.Cheng@advantech.com.tw)